

MACHINE EVALUATION REPORT



| MACHINE DATA | |
|-------------------|-------------------|
| Manufacturer | BELL |
| Product Group | DUMPER TRUCK |
| Model | B40D 6X6 |
| Serial Number | 981-00-371478 |
| Year Manufactured | 2005 |
| Year bought | |
| SMR | 11302 |
| Engine model | 941-981-00-379339 |
| Engine S/N | |

| GENERAL INFORMATION | |
|---------------------------|-----------|
| Date of inspection | 08-Feb-09 |
| Name of inspector | MALAN |
| Customer name | |
| Contact | |
| Location | KALGOLD |
| Type of usage / applicat. | |
| Expected entry date | |
| Expected SMR | |

| MACHINE MAIN SPECS | |
|--------------------|----------------|
| Body Type | |
| Body Capacity | m ³ |
| Body Extension | mm |
| Cab: | |
| Tire Size & type | |
| Tire Brand | |
| Dump Trucks Type | |

| STAR RATING | | | | |
|-----------------------------|---------|---------|---------|--------|
| EX | GOOD | FAIR | AV | POOR |
| XXXXX | XXXX | XXX | XX | X |
| 90% + | 70 - 90 | 50 - 70 | 40 - 50 | < 40 % |
| MAIN COMPONENT CONDITION | | | | |
| Exterior | | | | |
| Cab | | | | |
| Right Front Tire | | | | |
| Left Front Tire | | | | |
| Right Rear Tire | | | | |
| Left Rear Tire | | | | |
| Right Mid Tire | | | | |
| Left Mid Tire | | | | |
| Under Carriage Left | | | | |
| Under Carriage Right | | | | |
| Engine Performance | | | | |
| Electric System | | | | |
| Hydraulic Performance | | | | |
| Working Attachments | | | | |
| Dumper assay | | | | |
| Drive Train | | | | |
| Safety Items & Compliance | | | | |
| Main Frame | | | | |
| Steering Cylinder & Linkage | | | | |
| Paint Condition | | | | |
| Heater / Air Conditioner | | | | |
| Warning Lights | | | | |
| Transmission | | | | |
| Torque converter | | | | |
| Final Drives | | | | |
| Service Brakes | | | | |
| Parking Brake | | | | |
| Gauges | | | | |

| Plant | D | T | 1 | 3 | 2 |
|-------|---|---|---|---|---|
| P | S | | | | |

| COMPLIANCES | YES | NO |
|----------------|-----|----|
| O & M Manual | | X |
| CE Plate | | X |
| CE Certificate | | X |
| ROPS Plate | | X |
| Others | | X |

| SERVICE RECORDS | YES | NO |
|---------------------------|-----|----|
| Mach. History | X | |
| Good state of maintenance | X | |

| CURRENT EVALUATION | |
|----------------------|------|
| Mach. Age (Years) | 4 |
| Avg hrs / year (Hrs) | 2664 |

| GENERAL REMARKS: | |
|------------------|--|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |

| 1. FRONT RIGHT |
|----------------|
| |



| 3. REAR LEFT |
|--------------|
| |

| 4. REAR RIGHT |
|---------------|
| |

| 5. CAB COMPARTMENT |
|--------------------|
| |

| 6. BIN / BLADE / RIPPER |
|-------------------------|
| |

| | | | |
|--|--|---------------------------|----------------|
| www.alsplantsales.co.za | Phone Johan: 082 450 0451 / 018 290 8070 | OUR NET PRICE (VAT EXCL.) | R 1,550,000.00 |
|--|--|---------------------------|----------------|

Whilst every effort has been made by ALS Plant Sales to ensure the accuracy of the information/images displayed. The availability of products offered or accuracy cannot be guaranteed. Prices are subject to change without prior notice. Pictures are only a representation of products and may not be an exact resemblance.